

Charging Indication

When the PT200 is connected to an AC adapter, the LED will blink GREEN (1 second ON, 3 seconds OFF) when charging and indicate solid GREEN when charging is complete.

It takes approximately 1.5 hours to charge the small battery and approximately 3 hours for the large battery. It charges in the same amount of time whether on the device or on a desktop charger